


The PCB concentrations noted below are from samples collected at approximately 1.5 m intervals at the base of the interim action excavation. These results will be considered in developing the upcoming site-wide investigation plan. For reference, Sample Stations S-12 through S-20 indicate positions of previous soil sampling.



Not to Scale

^aResult includes sum of Aroclors 1254 and 1260. For all other samples, only Aroclor 1254 was detected.



Figure 5. Residual PCB Contamination, GTSP/NBF Fenceline

Source: Integral 2006